

10-5-22	East Dam	- 26	DRS
10-5-22	West	Visual	DRS
10-5-22	Seabright	1.55	DRS
10-5-22	Montgomery	Visual	DRS
10-11-22	East Dam	- 27	DRS
10-11-22	West Dam	Visual Normal	DRS
10-11-22	Seabright	1.45	DRS
10-11-22	Montgomery	Visual Normal	DRS
10-12-22	East Dam	- 27	DRS
10-12-22	Seabright	1.45	DRS
10-12-22	West Dam	Visual Normal	DRS
10-12-22	Montgomery	Visual Normal	DRS
10-13-22	East Dam	- 27	DRS
10-13-22	West Dam	Visual Normal	DRS
10-13-22	Seabright	1.45	DRS
10-13-22	Montgomery	Visual Normal	DRS
10-14-22	Montgomery	Visual Normal	DRS
10-14-22	Seabright	1.55	DRS
10-14-22	East Dam (rain)	- 27	DRS
10-14-22	East Dam (rain)	- 20	DRS AM
10-17-22	East Dam	water moving under stones East of gate - 21	DRS
10-17-22	West Dam	Visual ok	DRS
10-17-22	Seabright	1.5	DRS
10-17-22	Montgomery	Rain to start tonight Gate open	DRS
10-18-22	East Dam (rain .44")	- 20	DRS
10-18-22	West Dam	Visual ok	DRS
10-18-22	Seabright	1.65	DRS
10-18-22	Montgomery	gate open	DRS
10-19-22	East	- 17	DRS
10-19-22	West	Visual ok	DRS
10-19-22	Seabright	1.6	DRS
10-19-22	Montgomery	Visual ok	DRS
10-20-22	East	- 16	DRS
10-20-22	West	Visual ok	DRS
10-20-22	Seabright	1.6	DRS
10-20-22	Montgomery	Visual ok	DRS

msg from smiling cow called to have the gate opened
 opened gate for rain

East @ 15"
West @ 12"

→ = 3" per
24 hr period
lake level
drop. with
no rain

Emailed Richelle
to remove leaves

Need leaves
removed

called Richelle
about the leaves

Rain tomorrow

Probe
being pulled
into gate

11-3-22	East Gate	-16	gate @ 15"	DRS
11-3-22	West	need leaves removed	gate @ 12"	DRS
11-3-22	Seabright	1.7		DRS
11-3-22	Montgomery	gate open		DRS
11-4-22	East gate Dam	-18	closed to 2"	DRS
11-4-22	West gate Dam	@ 12"	Set to 8"	DRS
11-4-22	Seabright	1.6"		DRS
11-4-22	Montgomery	gate open		DRS
11-7-22	East Dam	@ 18"	opened from 2" to 5"	DRS
11-7-22	West Dam		set to 8"	DRS
11-7-22	Seabright	2.3		DRS
11-7-22	Montgomery	open		
11-8-22	East	-19"	open to 5"	DRS
11-8-22	West		open to 8"	DRS
11-8-22	Seabright	2.3		DRS
11-8-22	Montgomery	open		DRS
11-12-22	East	-20"	open to 5"	DRS
11-12-22	West	Visual	open to 8"	DRS
11-12-22	Seabright	2.4		DRS
11-12-22	Montgomery	Open		DRS
11-12-22	East	-15"	open to 5"	DRS
11-14-22	West	Visual	open to 8"	DRS
11-14-22	Seabright	2.45		DRS
11-14-22	Montgomery	Visual	gate open	DRS
11-15-22	East	-15"	open to 5" then to 9"	DRS
11-15-22	West		opened to 8"	DRS
11-15-22	Seabright	2.35		DRS
11-15-22	Montgomery	gate open	Visual	DRS
11-16-22	East	-15"	open to 9"	DRS
11-16-22	West	-8"		DRS
11-16-22	Seabright	2.5		DRS
11-16-22	Montgomery	gate open		DRS
11-17-22	East	-13"	open to 9"	DRS
11-17-22	West	at 8"	Set to 12"	DRS
11-17-22	Seabright	2.5		DRS
11-17-22	Montgomery	Open		DRS

gate set at

Water levels

91

11-18-22	East Dam	16" was at 13"	-13	DBS
11-18-22	West Dam	was at 12"		DBS
11-18-22	Sea Bright	2.6"		DBS
11-18-22	Montgomery	gate open		DBS
11-21-22	East Dam	gate 16"	-19.5	DBS
11-21-22	West Dam	12"		
11-21-22	Seabright		2.7	DBS
11-21-22	Montgomery	gate open	Full spillway	DBS
11-22-22	East Dam	gate 16"	-22	
11-22-22	West Dam	gate 12" set to 8"		DBS
11-22-22	Seabright		2.7	DBS
11-22-22	Montgomery	open		
11-23-22	East	gate 16" set to 1.5"	-23.5	DBS
11-23-22	West	8"		DBS
11-23-22	Seabright		2.3	DBS
11-23-22	Montgomery			
11-28-22	Seabright		2.3	DBS
11-28-22	East Dam	1.5	-23	DBS
11-28-22	West Dam	8		
11-28-22	Montgomery	gate open - needed to remove Board + Conduit stuck in gate called MDEP UST about tank		
11-29-22	Seabright	Usual	2.3	DBS
11-29-22	East	1.5	-20	DBS
11-29-22	West	closed set to 13.5"		DBS
11-29-22	Montgomery	closed		DBS
12-2-22	East	gate set to 10"	-18	DBS
12-2-22	West	west 13.5"	13.5"	
12-2-22	Seabright		2.4	
12-2-22	Seabright	closed gate		
12-5-22	East	gate 10"	Elevation - 8"	DBS
12-5-22	West	13.5"	13.5"	
12-5-22	Seabright	usual	2.6	
12-5-22	Montgomery	closed		

gate 6 hrs

			Gate	Water Level
E-mailed Michelle Gasal about clearing leaves	12-6-22	East	19"	-8
	12-6-22	West	20.5"	
	12-6-22	Seabright		2.7
	12-6-22	Montgomery	opened gate	
	12-7-22	East	19"	-9
	12-7-22	West		3.1
	12-7-22	Seabright		3.1
	12-7-22	Montgomery		
2" of rain log + leaves on grate touching smiling row	12-8-22	East	19"	-4
	12-8-22	West	20.5"	
	12-8-22	Seabright		3.2
	12-8-22	Montgomery	open	
	12-9-22	East	19"	-3.5
	12-9-22	West	20.5"	
	12-9-22	Seabright		3.0
	12-9-22	Montgomery	open	
E-mailed Michelle about clearing the West Grate	12-12-22	East	19"	-10.5
	12-12-22	West	20.5	
	12-12-22	Seabright	visual	3.0
	12-12-22	Montgomery	Gate open	
	12-13-22	East	19"	-12
	12-13-22	West	20.5"	
	12-13-22	Seabright	Visual	2.9
	12-13-22	Montgomery	Gate open	
	12-15-22	East	19"	-17
	12-15-22	West	20.5"	
	12-15-22	Seabright	Visual	2.8
	12-15-22	Montgomery	gate open	

Water Level	Gate	Level
-8	East	-19"
	West	20.5"
3.7	Seabright	Visual
	Montgomery	2.8
-9	East	-19"
	West	20.5"
3.1	Seabright	Visual
	Montgomery	2.8
-4	East	-20.5"
	West	20.5
3.2	Seabright	Visual
	Montgomery	Visual
-3.5	East	-19
	West	20.5
3.0	Seabright	Visual
	Montgomery	Visual
10.5	East	-19
	West	20.5
3.0	Seabright	
	Montgomery	
-12	East	-19
	West	20.5
2.9	Seabright	Visual
	Montgomery	
-17	East	-19
	West	20.5
	Seabright	Visual
	Montgomery	closed dam
	East	19
	West	20.5 Visual
	Seabright	Visual
	Montgomery	closed

not
affected

low
low low

not to
on the
etc

		Gate	Level
	12-30-22	East 19	-24
	12-30-22	West was 20 set to 3	
	12-30-22	Seabright	2.7
	12-30-22	Montgomery closed	
	1-3-22	East was 19" set to 2"	-22
	1-3-22	West 3"	
	1-3-22	Seabright	2.1
	1-3-22	Montgomery closed	
	1-4-22	East set to 2"	-22
	1-4-22	West 3"	
	1-4-22	Seabright	2.1
	1-4-22	Montgomery closed	
	1-5-22	East set to 2"	-21
	1-5-22	West was at 3" set to 6"	
	1-5-22	Seabright	2.1
	1-5-22	Montgomery	
1" of snow	1-6-22	East set to 2"	-20
	1-6-22	West was 6" set to 8"	
	1-6-22	Seabright	
	1-6-22	Montgomery	
	1-7-22	East 2"	-18
	1-7-22		
	1-7-22		
	1-7-22		
	1-9-22	East set to 2"	-20
	1-9-22	West set to 9"	
	1-9-22	Seabright	2.3
	1-9-22	Montgomery visual	

	1-10-22	East	Set to 2"	-20
	1-10-22	West	Set to 8"	
	1-10-22	Seabright		2.3
	1-10-22	Montgomery	Visual	
	1-11-22	East	2"	-20
acked	1-11-22	West	was 8" set 10"	
	1-11-22	Seabright		2.3
	1-11-22	Montgomery		
	1-12-22	East	2"	-21
	1-12-22	West	10"	
	1-12-22	Seabright		2.3
	1-12-22	Montgomery		
of as of	1-13-22	East	was 2" to 8"	-19
	1-13-22	West	10"	
	1-13-22	Seabright		2.3
order to smily and 15 under	1-13-22	Montgomery	corner of smily row under under	
	1-17-22	East	8"	-16
of	1-17-22	West	10"	2.5
	1-17-22	Seabright		2.5
	1-17-22	Montgomery		
	1-18-22	East	8"	-10
	1-18-22	West	10"	2.5
	1-18-22	Seabright		2.5
	1-18-22	Montgomery	Visual	
	1-19-22	East	8"	-10
	1-19-22	West	10"	
	1-19-22	Seabright		2.5
	1-19-22	Montgomery	Visual	

at snow

1/20/23

			Gate setting	level
16" of snow on 1-23-23	1-24-23	East	8"	-13
	1-24-23	West	10"	
	1-24-23	Seabright		2.6
	1-24-23	Montgomery	visual ok	
	1-25-23	East	8"	-14
	1-25-23	West	10"	
	1-25-23	Seabright		2.6
	1-25-23	Montgomery	Visual ok	
Smiling cow under water	1-26-23	East	19"	-12
	1-26-23	West	18"	
	1-26-23	Seabright		3.2
	1-26-23	Montgomery	⊗	
At spillway	1-27-23	East	19"	0
	1-27-23	West	18"	
	1-27-23	Seabright		3.1
	1-27-23	Montgomery	visual ok	
Smiling cow water at bottom	1-30-23	East	19"	0
	1-30-23	West	18"	
	1-30-23	Seabright		3.1
	1-30-23	Montgomery	Visual ok	
	1-31-23	East	19"	-2
	1-31-23	West	18"	
	1-31-23	Seabright		3.1
	1-31-23	Montgomery		
Cleaned snow off all catwalks	2-1-23	East	19"	-4
	2-1-23	West	18"	
	2-1-23	Seabright		3.1
	2-1-23	Montgomery		

	2-2-23	East	19"	-7
	2-2-23	West	18"	
	2-2-23	Seabright		2.6
	2-2-23	Montgomery		
19	2-6-23	East	6"	-18 $\frac{1}{2}$
	2-6-23	West	18"	
	2-6-23	Seabright	could not read due to ice	
	2-6-23	Montgomery	visual OK	
12	2-7-23	East	6"	-19
	2-7-23	West	18"	
	2-7-23	Seabright		2.6
	2-7-23	Montgomery	visual	
0	2-8-23	East	6"	-22
	2-8-23	West	18"	
	2-8-23	Seabright		
	2-8-23	Montgomery	visual	
	2-9-23	East	6"	-22
	2-9-23	West	18"	
	2-9-23	Seabright		2.6
	2-9-23	Montgomery	visual	
2	2-14-23	East	6"	23
	2-14-23	West	18"	
3-1	2-14-23	Seabright		2.6
	2-14-23	Montgomery	visual	
4	2-15-23	East	6"	24
	2-15-23	West	18"	
31	2-15-23	Seabright		2.6
	2-15-23	Montgomery	visual	

Locked at 25 main st pipe from mill pond discharging under 25 main due to broken outfall elbow at 25 main will need to drain mill pond to confirm	2-16-23	East	6"	24
	2-16-23	West	18"	
	2-16-23	Seabright		2.65
	2-16-23	Montgomery	usual	
	2-17-23	East	6"	
	2-17-23	West	10"	
	2-17-23	Seabright		2.65
	2-17-23	Montgomery	usual	



2-21-23	East	6"	24"
2-21-23	West	18"	
2-21-23	Seabright		2.6
2-21-23	Montgomery		
2-22-23	East	6"	25'
2-22-23	West	18"	
2-22-23	Seabright		2.6
2-22-23	Montgomery		
2-28-23	East	6"	32"
2-28-23	West	18" Set to 6"	
2-28-23	Seabright		not readable ice
2-28-23	Montgomery		ok
3-3-23	East	6"	32"
3-3-23	West	6"	
3-3-23	Seabright		not readable
3-3-23	Montgomery		ok

3-6-23	East	6"	34"
3-6-23	West	6"	
3-6-23	Seabright		not readable
3-6-23	Montgomery		OK
3-7-23	East	6"	34"
3-7-23	West	6"	
3-7-23	Seabright		not readable
3-7-23	Montgomery		OK
3-8-23	East	6"	34
3-8-23	West	6"	
3-8-23	Seabright		not readable
3-8-23	Montgomery		OK
3-9-23	East	6"	34
3-9-23	West	6"	
3-9-23	Seabright		not readable
3-9-23	Montgomery		OK
3-13-23	East	6"	34
3-13-23	West	6"	
3-13-23	Seabright		not readable
3-13-23	Montgomery		OK
3-19-23	East	Set to 1.5"	34"
3-19-23	West	Set to 1"	
3-19-23	Seabright		2.3
3-19-23	Montgomery		OK
3-20-23	East	1.5"	32"
3-20-23	West	1"	
3-20-23	Seabright		1.8"
3-20-23	Montgomery		OK

opened the mill pond to inspect under Lee Montgomery's building surroundings. the water flow stopped after mill pond was empty. Found an Inlet Gate up against once a tree in the mill pond which is the "source" of water

592-5992 ->	3-21-23	East	1.5"	31.5
Micki Colnon	3-21-23	West	1"	
Megant:cook lake	3-21-23	Seabright		1.75
Waterland Association	3-21-23	Montgomery		OK
Called about low lake levels, explained the work being done down river and the policy of keeping lake low for farm events. Said I would begin keeping lake level up.	3-23-23	East	1.5"	28
	3-23-23	West	1"	
	3-23-23	Seabright		1.75
	3-23-23	Montgomery		OK
	3-24-23	East	1.5"	26
	3-24-23	West	1"	
	3-24-23	Seabright		1.8
	3-24-23	Montgomery		OK
	3-27-23	East	1.5"	18"
	3-27-23	West	1"	
slides on spillway	3-27-23	Seabright		1.8
	3-27-23	Montgomery		OK
	3-28-23	East	1.5"	15.5"
	3-28-23	West	1"	
	3-28-23	Seabright		1.8
	3-28-23	Montgomery		OK
	3-29-23	East	1.5"	13"
	3-29-23	West	1"	
	3-29-23	Seabright		1.8
	3-29-23	Montgomery		OK
	3-30-23	East	1.5"	12"
	3-30-23	West	1"	
	3-30-23	Seabright		1.8
	3-30-23	Montgomery		OK

Water level	Date	Location	Dam Gate	Water level
31.5	4-2-23	East	1.5'	-4
	4-2-23	West	1"	
1.75	4-2-23	Seabright		1.8
OK	4-2-23	Montgomery		OK
18	4-3-23	East	1.5"	-2
	4-3-23	West	1"	
25	4-3-23	Seabright		1.8
	4-3-23	Montgomery		OK
16	4-4-23	East	1.5"	-1
about	4-4-23	West	1"	
spill way	4-4-23	Seabright		1.8
	4-4-23	Montgomery		OK
9"	4-5-23	East	1.5"	+1
	4-5-23	West	1"	
1.3	4-5-23	Seabright		1.8
	4-5-23	Montgomery		OK
5"	4-6-23	East	1.5"	+2
	4-6-23	West	1"	
1.3	4-6-23	Seabright		1.8
	4-6-23	Montgomery		OK
3"	4-7-23	East	1.5"	+3
	4-7-23	West	1"	
1.3	4-7-23	Seabright		1.8
	4-7-23	Montgomery		OK
2"	4-10-23	East	1.5"	+5
	4-10-23	West	1"	
1.3	4-10-23	Seabright		1.8
	4-10-23	Montgomery		OK


Date	Location	Wind	Water level
4-12-23	East	1.5"	+5.5
4-12-23	West	1"	
4-12-23	Seabright		2.2
4-12-23	Montgomery		ok
4-17-23	East	1.5"	+5.5
4-17-23	West	2"	
4-17-23	Seabright		2.2
4-17-23	Montgomery		ok
4-18-23	East	1.5"	+6
4-18-23	West	2"	
4-18-23	Seabright		2.3
4-18-23	Montgomery		ok
4-19-23	East	1.5"	+6
4-19-23	West	2"	2.2
4-19-23	Seabright		↓
4-19-23	Montgomery		ok
4-20-23	East	1.5"	+6
4-20-23	West	2"	2.2
4-20-23	Seabright		↓
4-20-23	Montgomery		ok
4-21-23	East	1.5	+6
4-21-23	West	2	↓
4-21-23	Seabright		2.2
4-21-23	Montgomery		ok
4-22-23	East	1.5	+6
4-22-23	West	2	
4-22-23	Seabright		2.2
4-22-23	Montgomery		ok

		Dam Gate	Water level
	4-23-23	East 1.5'	+6
	4-23-23	West 2"	
	4-23-23	Seabright	2.2
	4-23-23	Montgomery	04
• 6" of Rain	4-25-23	East 1.5'	+7.5
	4-25-23	West at 2 opened to 4	
Tim Hetner	4-25-23	Seabright	2.4
352-598-3357	4-25-23	Montgomery	04
Wants lake lower		Removed beam (abdom)	
Lincolntonville	4-26-23	East 1.5	+8
Poland Rd #68	4-26-23	West 4	04
	4-26-23	Seabright	2.3.5
	4-26-23	Montgomery	04
	4-27-23	East 1.5	+7
	4-27-23	West 4	04
	4-27-23	Seabright	2.4
	4-27-23	Montgomery	04
West	4-30-23	East 1.5	+6
dammed	4-30-23	West 4 open all the way	04
all the	4-30-23	Seabright	2.5
Way for	4-30-23	Montgomery	04
Storm			
4.2 inches			
	5-1-23	East (Broken, repaired) and opened all the way	+23
of rain over	5-1-23	West open all the way	at 10:00
night. stopped	5-1-23	Seabright	5.3
raining at 11 AM	5-1-23	Montgomery	
2+ inches			
in appleton			
Lincolntonville			
	5-2-23	East	+20
East Dam	5-2-23	West	open all the way
trash rack had	5-2-23	Seabright	5.0
canoe + kayak all	5-2-23	Montgomery	open all the way
+ 1000 blocks	5-2-23		
rack lake level			
1' higher on lake			
side of trash			
rack			

* had meeting on 5-1-23 with Police + Fire reviewed Emergency Action Plan. placed water level stakes and monitored water levels over night. placed down stream residents on Text

	Gate	level
5-3-23	East	Open all the way + 17
5-3-23	West	Open all the way
5-3-23	Seabright	4.8
5-3-23	Montgomery	Open all the way
<p>Removed 1 canoe blocking the east dam grate 3 logs + a kayak. The items were blocking the rack raising the lake level not allowing water to get to the actual east dam. Come alongs were used difficult task took 3 hours 4 people</p>		
5-4-23	East	Open all the way + 15
5-4-23	West	Open all the way
5-4-23	Seabright	4.5
5-4-23	Montgomery	Open all the way
5-5-23	East	Open all the way + 12
5-5-23	West	Open all the way
5-5-23	Seabright	4.3
5-5-23	Montgomery	Open all the way

meeting at Dam 5-5-23

Lyle Devoe
 Roger Wickenden
 Chip Lantz
 Paul Cheep
 Brian Wickenden
 Wendy Wickenden
 Dwayne Shaw
 Micki Colquhoun
 Gary Gates CMCT
 Tom Trumbauer MWA


level
4.8

called
about cleaning
with gates 5-8-23



Lowered/closed
12"
Lowered
8"

East
West
Seabright
Montgomery

Gate

was open all the way set to 12"
was open all the way set to 16"

level

+4
+3.5
ok

ack
SS
people

5-9-23
5-9-23
5-9-23
5-9-23

East
west
Seabright
Montgomery

12"
was at 16" set to 20"

+5
+3.2

15
15

5-10-23
5-10-23
5-10-23
5-10-23

East
West
Seabright
Montgomery

was at 20" set to 18"

+2
+3.1

13